

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 82 Category: 3

 Assessment Date:
 25/10/1996
 Last Revision Date:
 27/10/2009

 HCWA Number:
 13338
 Asset ID:
 MCH126484

PLACE DETAILS

Name: House

Other Names: 11 Conway Street

Type of Place: House

Address: 11 Conway Street

Suburb: Beachlands

LOCATION

Map 14.14 GPS 6813898.00 GPS 265825.000

Reference: Northing: 0000 Easting: 000



Photo Description:

20/11/2007 Rod Milne

Feature decoration to gable end.

Generated: 13/12/2018 Page 1 of 4

SITE DETAILS

Lot No.: Lot 527

Reserv No.: Assess No.: 10373

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

DESCRIPTION

Walls: Brick Roof: Corrugated Iron

Condition: Good Integrity:

Original fabric:

Modifications: Verandah enclosures removed

This brick house has a corrugated iron gambrel roof with a separate gable roof to the north east. The gable end has stucco infill with a decorative diamond shaped feature. The main roof extends to cover the front verandah to the north west and this roof extends to the east below the gable end to form an eaves overhang. Windows are timber framed and double hung. There is a brick corbelled chimney to the south east.

HISTORY

Construction Date: 1917 **Source:** Owner

Architect: Unknown Builder: Unknown

The house was built in c1917.

HISTORIC THEMES

HCWA: 104 Land allocation and subdivision

AHC: 4.1.2 Making suburbs

Generated: 13/12/2018 Page 2 of 4

STATEMENT OF SIGNIFICANCE

This simple character house with its original gambrel roof structure, corbelled brick chimney and gable end detail contributes positively to the streetscape of the locale.

MANAGEMENT CATEGORY

Management Category: 3

Level of Significance: MODERATE SIGNIFICANCE: Important to the

heritage of the locality.

ManagementConservation of the place is recommended. **Recommendation:**Any proposed change to the place should not

unduly impact on the heritage values of the place and should retain significant fabric

wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS

Generated: 13/12/2018 Page 3 of 4



Photo Description: 25/10/1996 Suba & Grundy View showing verandah enclosures to front facade.

Generated: 13/12/2018 Page 4 of 4