

# City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 87 Category: 3

 Assessment Date:
 25/10/1996
 Last Revision Date:
 27/10/2009

 HCWA Number:
 13342
 Asset ID:
 MCH126499

## **PLACE DETAILS**

Name: House

Other Names: 1 Crowther Street

**Type of Place:** House

Address: 1 Crowther Street

**Suburb:** West End

## **LOCATION**

**Map** 14.14 **GPS** 6814097.00 **GPS** 265555.000

Reference: Northing: 0000 Easting: 000



## **Photo Description:**

13/04/2008

Tanya Henkel

Weatherboard cottage set behind picket fence.

Generated: 15/08/2019 Page 1 of 4

#### SITE DETAILS

Lot No.: Lot 3

Reserv No.: Assess No.: 10515

Dia/Plan: Vol/Fol:

## **USE OF PLACE**

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

#### **DESCRIPTION**

Walls: Weatherboard Roof: Corrugated Iron

**Condition:** Good **Integrity:** 

Original fabric:

**Modifications:** Verandah pitch, cladding and posts

This is a small timber framed weatherboard clad cottage with a galvanised iron gambrel roof with slatted gablets. The main roof extends to the rear as a broken back skillion roof. A weatherboard clad extension to the rear has a gable roof with a small skillion roof below the east gable end which marries to the skillion roof of the main building. To the front facade a separate shallow pitched shadowline clad verandah roof is supported on chamfered timber posts. Windows are timber framed and double hung. There are two large Norfolk Island Pines (Araucaria heterophylla) to the street verge in front of the cottage. A timber picket fence forms the front property boundary.

# **HISTORY**

Construction Date: unknown Source:

Architect: Unknown
Builder: Unknown

No History Available.

#### HISTORIC THEMES

**HCWA:** 104 Land allocation and subdivision

Generated: 15/08/2019 Page 2 of 4

AHC: 4.1.2 Making suburbs

#### STATEMENT OF SIGNIFICANCE

This simple house has considerable aesthetic appeal given that it has retained much of its original fabric including its weatherboard cladding, corbelled brick chimney and gambrel roof form. As such the place contributes to the built environment of the locale.

#### MANAGEMENT CATEGORY

**Management Category:** 3

**Level of Significance:** MODERATE SIGNIFICANCE: Important to the

heritage of the locality.

ManagementConservation of the place is recommended.Recommendation:Any proposed change to the place should not

unduly impact on the heritage values of the place and should retain significant fabric

wherever feasible.

#### OTHER LISTINGS

No other listings

#### SUPPORTING INFORMATION

#### OTHER PHOTOS

Generated: 15/08/2019 Page 3 of 4



# Photo Description: 25/10/1996

25/10/1996 Suba & Grundy

Unsympathetic asbestos fence and metal verandah poles since removed.

Generated: 15/08/2019 Page 4 of 4