

# City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 341 Category: 4

 Assessment Date:
 05/11/1996
 Last Revision Date:
 11/03/2010

 HCWA Number:
 13733
 Asset ID:
 MCH127041

## **PLACE DETAILS**

Name: House

Other Names: 2 Ruby Street

**Type of Place:** House

Address: 2 Ruby Street Suburb: Geraldton

## **LOCATION**

Map 15.14 GPS 6815124.00 GPS 267140.000

Reference: Northing: 0000 Easting: 000



## **Photo Description:**

31/10/2007

Rod Milne

Front verandah enclosed with fibro sheeting.

Generated: 15/08/2019 Page 1 of 4

# **SITE DETAILS**

Lot No.: Lot 11

Reserv No.: Assess No.: 11808

Dia/Plan: Vol/Fol:

## **USE OF PLACE**

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

#### **DESCRIPTION**

Walls: Weatherboard/Fibro Roof: Corrugated Iron

Condition: Good Integrity:

Original fabric:

**Modifications:** Verandah enclosed

This small timber framed house is clad with weatherboard and fibro and has a hipped corrugated iron roof and a separate skillion verandah roof to the rear and front elevations. There is weatherboard cladding to the front facade with fibro to the other walls, including the verandah enclosures. The side windows have metal awnings, and there is a rendered brick chimney to the rear. The street boundary has a low rendered brick wall. The solar hot water system on the north roof is an intrusive element.

## **HISTORY**

**Construction Date:** unknown **Source:** Pat Johnston

Architect: Unknown Builder: Unknown

No History Available.

## **HISTORIC THEMES**

**HCWA:** 104 Land allocation and subdivision

200 Transport and communications

603 Local heroes and battlers

Generated: 15/08/2019 Page 2 of 4

AHC: 4.1.2 Making suburbs

3.8.5 Moving goods and people on land

3.5 Developing primary production

## STATEMENT OF SIGNIFICANCE

This house, although altered by the addition of verandah infill, is still representative of the style of housing of its era. The original weatherboard cladding to the front facade, the feature chimney and window awnings are still evident. The house adds to the streetscape and character of this locale.

## MANAGEMENT CATEGORY

Management Category:

Level of Significance: SOME SIGNIFICANCE: Contributes to the

heritage and/or historical development of the

locality.

Management Recommendation: Conservation of the place is desirable. Any proposed change to the place should be in

sympathy with the heritage values of the place.

## **OTHER LISTINGS**

No other listings

## SUPPORTING INFORMATION

Bibliography:

HCWA Database No. 13942.

#### OTHER PHOTOS

Generated: 15/08/2019 Page 3 of 4



Photo Description: 5/11/1996 Suba & Grundy Corner view of house.

Generated: 15/08/2019 Page 4 of 4