

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area:	Geraldton	Place Nur	nber:	352	Cate	egory:	2	
Assess	ment Date:	24/10/1996	Last	Revision	Date:	11/0	3/201	0
HCWA	Number:	13744	Asse	et ID:		MCH	11268	53

PLACE DETAILS

Name:	House
Other Names:	94 Sanford Street, cnr Cathedral Avenue
Type of Place:	House
Address:	94 Sanford Street, cnr Cathedral Avenue
Suburb:	Geraldton

Map 15.15 GPS 6814473.00 GPS 266737.000 Reference: Northing: 0000 Easting: 000



Photo Description: 21/01/2010 Tanya Henkel Prominent corner location.

SITE DETAILS

Lot No.:	Lot 5		
Reserv No.: Dia/Plan:		Assess No.: Vol/Fol:	20592

USE OF PLACE

Original Use: Current Use:	Residence Office		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Weatherboard	Roof:	Zincalume
Condition:	Good	Integrity:	
Original fabric Modifications:		replaced	

Situated on prominent corner location, this large timber framed and weatherboard clad house has a zincalume hipped roof which extends to cover the surrounding verandahs which are supported on turned timber posts. The main entry addressing Sanford Street is enhanced with feature gable and archway. Windows are timber framed and double hung. Two rendered corbelled chimneys punctuate the roofscape. A rammed limestone extension was constructed to the rear in 2004. There is a low masonry retaining wall to the street boundaries.

HISTORY			
Construction Date: Architect: Builder:	unknown Unknown Unknown	Source:	
No History Available.			

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

Given its large size, prominent location and use of decorative elements such as turned timber posts and corbelled chimneys this house has high aesthetic significance. The place makes a positive contribution to the built environment of the area.

MANAGEMENT CATEGORY

Management Category: Level of Significance:	2 CONSIDERABLE SIGNIFICANCE: Very important to the heritage of the locality.
Management Recommendation:	Conservation of the place is highly recommended. Any proposed change should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS



Photo Description: 3/08/2007 Rod Milne

Prior to removal of tiled roof.



Photo Description: 24/10/1996 Suba & Grundy Tiled roof which was replaced with zincalume in 2009.