

<b>Area:</b> Geraldton	<b>Place Number:</b> 105	<b>Category:</b> 3
<b>Assessment Date:</b> 24/10/1996	<b>Last Revision Date:</b> 28/10/2009	
<b>HCWA Number:</b> 13357	<b>Asset ID:</b> MCH126565	

### PLACE DETAILS

<b>Name:</b>	House
<b>Other Names:</b>	61 Durlacher Street
<b>Type of Place:</b>	House
<b>Address:</b>	61 Durlacher Street
<b>Suburb:</b>	Geraldton

### LOCATION

<b>Map Reference:</b> 15.14	<b>GPS Northing:</b> 6814736.00	<b>GPS Easting:</b> 266952.000
	<b>GPS Easting:</b> 0000	<b>GPS Easting:</b> 000



#### Photo Description:

18/12/2007

Rod Milne

Brickwork painted light blue.

## SITE DETAILS

<b>Lot No.:</b>	Lot 1144	<b>Assess No.:</b>	11752
<b>Reserv No.:</b>		<b>Vol/Fol:</b>	
<b>Dia/Plan:</b>			

## USE OF PLACE

<b>Original Use:</b>	Residence		
<b>Current Use:</b>	Residence		
<b>Ownership:</b>			
<b>Public Access:</b>	No	<b>Occupied:</b>	Occupied

## DESCRIPTION

<b>Walls:</b>	Brick	<b>Roof:</b>	Corrugated Iron
<b>Condition:</b>	Good	<b>Integrity:</b>	
<b>Original fabric:</b>	Pediment detailing		
<b>Modifications:</b>	Brickwork painted		

This brick residence has a corrugated iron gambrel roof with a separate gable which covers the main room to the front of the house. The gable end is finished in roughcast with timber battens. The front of the house is rendered and painted while the sides are painted brick. The main roof extends to cover a verandah which is hipped to the corner. The verandah is supported on timber posts and features a shallow arched frieze. There are two tapered chimneys with stucco render and a terracotta chimney pot above which punctuate the roof-scape. The windows to the main room are timber framed and double hung. There is a lean-to to the rear. A low masonry wall forms the front property boundary.

## HISTORY

<b>Construction Date:</b>	unknown	<b>Source:</b>	HCWA
<b>Architect:</b>	Unknown		
<b>Builder:</b>	Unknown		

No History Available.

## HISTORIC THEMES

<b>HCWA:</b>	104 Land allocation and subdivision
<b>AHC:</b>	4.1.2 Making suburbs

## STATEMENT OF SIGNIFICANCE

This house, one of two remaining on this section of Durlacher Street, retains most of its original fabric and form, and as such has aesthetic value. The place makes a positive contribution to the streetscape.

## MANAGEMENT CATEGORY

<b>Management Category:</b>	3
<b>Level of Significance:</b>	MODERATE SIGNIFICANCE: Important to the heritage of the locality.
<b>Management Recommendation:</b>	Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

## OTHER LISTINGS

No other listings

## SUPPORTING INFORMATION

GLLSPC - Geraldton (General).

## OTHER PHOTOS



**Photo Description:**

24/10/1996

Suba & Grundy

Verandah enclosures since removed.