

|                                    |                                       |                    |
|------------------------------------|---------------------------------------|--------------------|
| <b>Area:</b> Geraldton             | <b>Place Number:</b> 109              | <b>Category:</b> 4 |
| <b>Assessment Date:</b> 24/10/1996 | <b>Last Revision Date:</b> 28/10/2009 |                    |
| <b>HCWA Number:</b> 13360          | <b>Asset ID:</b> MCH126575            |                    |

### PLACE DETAILS

|                       |                      |
|-----------------------|----------------------|
| <b>Name:</b>          | Medical Centre       |
| <b>Other Names:</b>   | 150 Durlacher Street |
| <b>Type of Place:</b> | Medical Centre       |
| <b>Address:</b>       | 150 Durlacher Street |
| <b>Suburb:</b>        | Geraldton            |

### LOCATION

|                             |                                 |                                |
|-----------------------------|---------------------------------|--------------------------------|
| <b>Map Reference:</b> 15.14 | <b>GPS Northing:</b> 6814129.00 | <b>GPS Easting:</b> 267332.000 |
|                             | <b>GPS Northing:</b> 0000       | <b>GPS Easting:</b> 000        |



**Photo Description:**

19/11/2007

Rod Milne

View of front facade from Durlacher Street.

## SITE DETAILS

|                    |         |                    |       |
|--------------------|---------|--------------------|-------|
| <b>Lot No.:</b>    | Lot 964 | <b>Assess No.:</b> | 11448 |
| <b>Reserv No.:</b> |         | <b>Vol/Fol:</b>    |       |
| <b>Dia/Plan:</b>   |         |                    |       |

## USE OF PLACE

|                       |                |                  |          |
|-----------------------|----------------|------------------|----------|
| <b>Original Use:</b>  | Residence      |                  |          |
| <b>Current Use:</b>   | Medical Centre |                  |          |
| <b>Ownership:</b>     |                |                  |          |
| <b>Public Access:</b> | Restricted     | <b>Occupied:</b> | Occupied |

## DESCRIPTION

|                         |                         |                   |           |
|-------------------------|-------------------------|-------------------|-----------|
| <b>Walls:</b>           | Fibro                   | <b>Roof:</b>      | Colorbond |
| <b>Condition:</b>       | Not applicable          | <b>Integrity:</b> |           |
| <b>Original fabric:</b> |                         |                   |           |
| <b>Modifications:</b>   | Brick extension to rear |                   |           |

This is a small fibro cottage with a gambrel corrugated colorbond roof which extends to cover the front verandah. The verandah is supported on timber posts with decorative braces to the verandah beam. Windows are timber framed and double hung. There is a painted corbelled brick chimney to the south west.

## HISTORY

|                           |         |                |  |
|---------------------------|---------|----------------|--|
| <b>Construction Date:</b> | unknown | <b>Source:</b> |  |
| <b>Architect:</b>         | Unknown |                |  |
| <b>Builder:</b>           | Unknown |                |  |

No History Available.

## HISTORIC THEMES

|              |                                     |
|--------------|-------------------------------------|
| <b>HCWA:</b> | 104 Land allocation and subdivision |
| <b>AHC:</b>  | 4.1.2 Making suburbs                |

## STATEMENT OF SIGNIFICANCE

This small cottage retains much of its original form and fabric including its high pitched roof, tall corbelled chimney and decorative verandah braces. Accordingly the place contributes to the streetscape of the area.

## MANAGEMENT CATEGORY

|                                   |   |
|-----------------------------------|---|
| <b>Management Category:</b>       | 4   |
| <b>Level of Significance:</b>     | SOME SIGNIFICANCE: Contributes to the heritage and/or historical development of the locality.   |
| <b>Management Recommendation:</b> | Conservation of the place is desirable. Any proposed change to the place should be in sympathy with the heritage values of the place. |

## OTHER LISTINGS

No other listings

## SUPPORTING INFORMATION

## OTHER PHOTOS



**Photo Description:**

24/10/1996

Suba & Grundy

Aluminium tiled roof now replaced with colorbond.