

Area: Geraldton	Place Number: 121	Category: 3
Assessment Date: 06/11/1996	Last Revision Date: 30/10/2009	
HCWA Number: 13372	Asset ID: MCH126620	

PLACE DETAILS

Name:	House
Other Names:	64 Eastern Road
Type of Place:	House
Address:	64 Eastern Road
Suburb:	Geraldton

LOCATION

Map Reference: 15.15	GPS Northing: 6814508.00	GPS Easting: 267754.000
	GPS Northing: 0000	GPS Easting: 000



Photo Description:

19/12/2007

Rod Milne

Weatherboard house with bullnose verandah.

SITE DETAILS

Lot No.:	Lot 6	Assess No.:	15644
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Weatherboard/Fibro	Roof:	Corrugated Iron
Condition:	Not applicable	Integrity:	
Original fabric:			
Modifications:	New carport on the south side		

This is a timber framed weatherboard clad house with a corrugated iron gambrel roof with a skillion roof to the rear. There is a separate hipped bull nose verandah to the front which is supported on turned timber posts. A lean-to roof to the rear covers an extension which is enclosed with fibro. Internally the kitchen features jarrah wall paneling. A carport has been constructed to the south side of the house while a timber picket fence forms the front property boundary.

HISTORY

Construction Date:	unknown	Source:	
Architect:	Unknown		
Builder:	Unknown		

One of the first houses to be built in the area, it was a three room building consisting of a kitchen, lounge and bedroom, but has since been extended. There was originally a dairy to the rear, of which only a concrete floor remains. (Source: Owner Knowledge)
The original owner is believed to be Mrs Cant. (Source: Ann Boyle)

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

This house has historic significance as one of the oldest houses in the area and being part of a dairy farm at one time. It is of simple design and has retained its weatherboard cladding and bullnose verandah with turned timber posts. Given this the place has high integrity and makes an important contribution to the built environment of the area.

MANAGEMENT CATEGORY

Management Category:	3
Level of Significance:	MODERATE SIGNIFICANCE: Important to the heritage of the locality.
Management Recommendation:	Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS



Photo Description:

6/11/1996

Suba & Grundy

Verandah enclosures since removed.