

| | | |
|------------------------------------|---------------------------------------|--------------------|
| Area: Geraldton | Place Number: 83 | Category: 4 |
| Assessment Date: 25/10/1996 | Last Revision Date: 27/10/2009 | |
| HCWA Number: 13338 | Asset ID: MCH126487 | |

PLACE DETAILS

| | |
|-----------------------|------------------|
| Name: | House |
| Other Names: | 13 Conway Street |
| Type of Place: | House |
| Address: | 13 Conway Street |
| Suburb: | Beachlands |

LOCATION

| | | |
|-----------------------------|---------------------------------|--------------------------------|
| Map Reference: 14.14 | GPS Northing: 6813897.00 | GPS Easting: 265800.000 |
| | 0000 | 000 |



Photo Description:

20/11/2007
Rod Milne
Corner location.

SITE DETAILS

| | | | |
|--------------------|---------|--------------------|-------|
| Lot No.: | Lot 526 | Assess No.: | 10372 |
| Reserv No.: | | Vol/Fol: | |
| Dia/Plan: | | | |

USE OF PLACE

| | | | |
|-----------------------|-----------|------------------|----------|
| Original Use: | Residence | | |
| Current Use: | Residence | | |
| Ownership: | | | |
| Public Access: | No | Occupied: | Occupied |

DESCRIPTION

| | | | |
|-------------------------|-------------------|-------------------|-----------------|
| Walls: | Brick (Rendered) | Roof: | Corrugated Iron |
| Condition: | Good | Integrity: | |
| Original fabric: | | | |
| Modifications: | Painted brickwork | | |

This brick house has a gambrel corrugated iron roof with a slatted gable to the street facade. The roof below the gablet extends to cover the front verandah which is supported on metal posts. The centre of the verandah is enhanced by a gable, the gable end being roughcast. The verandah ends below the roof have lattice infill. The brick walls have been rendered and painted to the side with roughcast stucco finish to the front except below the windows which are painted brick. Windows are small paned casement style. There is a brick chimney to the rear and a garage attached to the east elevation. A fence of brick pier construction with iron infill forms the property boundary.

HISTORY

| | | | |
|---------------------------|---------|----------------|-----------------|
| Construction Date: | unknown | Source: | Owner Knowledge |
| Architect: | Unknown | | |
| Builder: | Unknown | | |

No History Available.

HISTORIC THEMES

| | |
|--------------|-------------------------------------|
| HCWA: | 104 Land allocation and subdivision |
|--------------|-------------------------------------|

AHC: 4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

This simple rendered brick house with its gambrel roof form and gable to the verandah contributes to the character of the Conway streetscape and the wider locale.

MANAGEMENT CATEGORY

| | |
|-----------------------------------|---|
| Management Category: | 4 |
| Level of Significance: | SOME SIGNIFICANCE: Contributes to the heritage and/or historical development of the locality. |
| Management Recommendation: | Conservation of the place is desirable. Any proposed change to the place should be in sympathy with the heritage values of the place. |

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS



Photo Description:

25/10/1996

Suba & Grundy

Roof gablets and small window panes a feature.