

<b>Area:</b> Geraldton	<b>Place Number:</b> 405	<b>Category:</b> 3
<b>Assessment Date:</b> 24/10/1996	<b>Last Revision Date:</b> 09/03/2012	
<b>HCWA Number:</b> 13798	<b>Asset ID:</b> MCH127130	

### PLACE DETAILS

<b>Name:</b>	House
<b>Other Names:</b>	138 Shenton Street
<b>Type of Place:</b>	House
<b>Address:</b>	138 Shenton Street
<b>Suburb:</b>	Beachlands

### LOCATION

<b>Map Reference:</b> 14.14	<b>GPS Northing:</b> 6813798.00	<b>GPS Easting:</b> 266371.000
	<b>GPS Northing:</b> 0000	<b>GPS Easting:</b> 000



**Photo Description:**

15/01/2008  
Rod Milne  
Elevated position.

## SITE DETAILS

<b>Lot No.:</b>	Lot 6	<b>Assess No.:</b>	10489
<b>Reserv No.:</b>	20649	<b>Vol/Fol:</b>	LR3148/875
<b>Dia/Plan:</b>	156216		

## USE OF PLACE

<b>Original Use:</b>	Residence		
<b>Current Use:</b>	Residence		
<b>Ownership:</b>	State Government		
<b>Public Access:</b>	No	<b>Occupied:</b>	Occupied

## DESCRIPTION

<b>Walls:</b>	Brick	<b>Roof:</b>	Corrugated Iron
<b>Condition:</b>	Good	<b>Integrity:</b>	
<b>Original fabric:</b>	Largely intact		
<b>Modifications:</b>			

Set above street level, this brick house has a corrugated iron gambrel roof and a skillion roof to a brick extension to the rear. To the front (south) elevation, a separate verandah roof is supported on timber posts. To the street facade, there is red face brickwork and french doors and awnings to side windows. The east wall has been rendered and there is a tall corbelled brick chimney to the north west. The front boundary has a stone retaining wall with a low concrete block wall and rendered brick piers set on top with picket infill.

## HISTORY

<b>Construction Date:</b>	unknown	<b>Source:</b>	
<b>Architect:</b>	Unknown		
<b>Builder:</b>	Unknwon		

No History Available

## HISTORIC THEMES

<b>HCWA:</b>	104 Land allocation and subdivision 407 Cultural activities
--------------	--

AHC: 4.1.2 Making suburbs  
8.5.4 Pursuing common leisure interests

### STATEMENT OF SIGNIFICANCE

This house, although altered, still retains much of its original features such as the high-pitched roof, exposed face brickwork, french doors and corbelled chimney. It enhances the streetscape of the area.

### MANAGEMENT CATEGORY

**Management Category:** 3  
**Level of Significance:** MODERATE SIGNIFICANCE: Important to the heritage of the locality.  
**Management Recommendation:** Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

### OTHER LISTINGS

No other listings

### SUPPORTING INFORMATION

### OTHER PHOTOS



**Photo Description:**

24/10/1996

Suba & Grundy

Elevated position.