

<b>Area:</b> Geraldton	<b>Place Number:</b> 370	<b>Category:</b> 4
<b>Assessment Date:</b> 24/10/1996	<b>Last Revision Date:</b> 12/03/2010	
<b>HCWA Number:</b> 13764	<b>Asset ID:</b> MCH126542	

### PLACE DETAILS

<b>Name:</b>	House
<b>Other Names:</b>	145 Shenton Street
<b>Type of Place:</b>	House
<b>Address:</b>	145 Shenton Street
<b>Suburb:</b>	Beachlands

### LOCATION

<b>Map Reference:</b> 14.14	<b>GPS Northing:</b> 6813729.00	<b>GPS Easting:</b> 266267.000
	<b>GPS Northing:</b> 0000	<b>GPS Easting:</b> 000



**Photo Description:**

20/11/2007

Rod Milne

Hidden behind tall fence.

## SITE DETAILS

<b>Lot No.:</b>	Lot 5	<b>Assess No.:</b>	10434
<b>Reserv No.:</b>		<b>Vol/Fol:</b>	
<b>Dia/Plan:</b>			

## USE OF PLACE

<b>Original Use:</b>	Residence		
<b>Current Use:</b>	Residence		
<b>Ownership:</b>			
<b>Public Access:</b>	No	<b>Occupied:</b>	Occupied

## DESCRIPTION

<b>Walls:</b>	Weatherboard	<b>Roof:</b>	Corrugated Iron
<b>Condition:</b>	Good	<b>Integrity:</b>	
<b>Original fabric:</b>			
<b>Modifications:</b>	Demolished		

Set behind a tall picket fence, this timber framed weatherboard clad house has a hipped corrugated iron roof with a separate hipped roof to the main room which extends to cover the front verandah and a lean-to roof to the rear. The verandah is supported on timber posts with decorative brackets to the verandah beam. Windows are a mixture of timber and aluminium frames.

## HISTORY

<b>Construction Date:</b>	unknown	<b>Source:</b>	
<b>Architect:</b>	Unknown		
<b>Builder:</b>	Unknown		

No History Available.

## HISTORIC THEMES

<b>HCWA:</b>	104 Land allocation and subdivision
<b>AHC:</b>	4.1.2 Making suburbs

## STATEMENT OF SIGNIFICANCE

Although set behind a tall picket fence, features such as the roof form, decorative braces to the verandah posts and surrounding verandahs combine to give the place streetscape value.

## MANAGEMENT CATEGORY

<b>Management Category:</b>	4
<b>Level of Significance:</b>	SOME SIGNIFICANCE: Contributes to the heritage and/or historical development of the locality.
<b>Management Recommendation:</b>	Conservation of the place is desirable. Any proposed change to the place should be in sympathy with the heritage values of the place.

## OTHER LISTINGS

No other listings

## SUPPORTING INFORMATION

## OTHER PHOTOS



**Photo Description:**

24/10/1996

Suba & Grundy

Solar hot water system since removed.