

Area: Mullewa	Place Number: 20	Category: 2
Assessment Date: 05/12/1996	Last Revision Date: 28/02/2012	
HCWA Number: 13250	Asset ID: MCH126533	

PLACE DETAILS

Name:	Shop
Other Names:	5 Jose Street
Type of Place:	Shop/Office?
Address:	5 Jose Street
Suburb:	Mullewa

LOCATION

Map	Mullewa	GPS	6817237.00	GPS	267458.000
Reference:	Townsite	Northing:	0000	Easting:	000



Photo Description:

15/11/2011

T. Henkel

Simple awning over entry and window openings.

SITE DETAILS

Lot No.:	Lot 26	Assess No.:	1442
Reserv No.:		Vol/Fol:	1955/838
Dia/Plan:			

USE OF PLACE

Original Use:	Shop/Office	Occupied:	Unknown
Current Use:	Not in use?		Occupancy
Ownership:	Unknown		
Public Access:	No		

DESCRIPTION

Walls:	Brick (Rendered)	Roof:	Zincalume
Condition:	Not applicable	Integrity:	
Original fabric:	Parapet detailing		
Modifications:	Windows replaced		

This small single storey commercial premise is of rendered brick construction with a hipped zincalume roof hidden behind a low, simple parapet. The front façade addressing Jose Street has a side entry door and two windows, above which is a flat awning. The original timber framed windows have been replaced with aluminium framed alternatives, with metal grilles in front. The building is painted predominantly cream with a Federation Red highlight colour.

HISTORY

Construction Date:	1930	Source:	Shirley Scotter
Architect:	Unknown		
Builder:	Unknown		

This house was built by Mr Evershed, an engine driver at Cumming Smith, Mt Lyle. (Source: Shirley Scotter)

HISTORIC THEMES

HCWA:	308 Commercial services and industries
--------------	--

STATEMENT OF SIGNIFICANCE

The building makes a valuable contribution to the streetscape with its simple parapet form and detailing. Although the windows and door have been replaced, the building remains highly original, is representative of construction of its era and reflects a growing prosperity in Mullewa at the time.

MANAGEMENT CATEGORY

Management Category:	2
Level of Significance:	CONSIDERABLE SIGNIFICANCE: Very important to the heritage of the locality.
Management Recommendation:	Conservation of the place is highly recommended. Any proposed change should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS

No other photos