

Area: Geraldton	Place Number: 270	Category: 4
Assessment Date: 06/11/1996	Last Revision Date: 27/11/2009	
HCWA Number: 13437	Asset ID: MCH127101	

PLACE DETAILS

Name:	House
Other Names:	32 Lorna Street
Type of Place:	House
Address:	32 Lorna Street
Suburb:	Beresford

LOCATION

Map Reference: 15.17	GPS Northing: 6817109.00	GPS Easting: 267751.000
	GPS Northing: 0000	GPS Easting: 000



Photo Description:

28/08/2007

Rod Milne

Original cottage form is still evident.

SITE DETAILS

Lot No.:	Lot 10	Assess No.:	14165
Reserv No.:		Vol/Fol:	1665/824
Dia/Plan:	222859		

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:	Unknown		
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Fibro	Roof:	Corrugated Iron
Condition:	Fair	Integrity:	
Original fabric:	External walls		
Modifications:			

This timber framed house has replacement fibro cladding, a corrugated iron gambrel roof with a large lean-to roof to the rear and a timber framed fibro clad addition to the north. To the front elevation a replacement flat verandah roof is supported on metal posts with a metal balustrade. Windows are aluminium framed.

HISTORY

Construction Date:	unknown	Source:	Original MI
Architect:	Unknown		
Builder:	Unknown		

This house was built by the Allens and was the birthplace of George K. Allen (after whom 'Allendale' was named). The house was later bought by Fred Hatherly. (Source: Joyce Milovitch, nee Hatherly)

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision 405 Sport, recreation and entertainment
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

Although the place has been significantly altered, the original form of the cottage is still evident. The high pitched roof still dominates the style of the place which has some value given it is an unusual style of construction for the area. The place appears to be one of the older residences in the suburb.

MANAGEMENT CATEGORY

Management Category:	4
Level of Significance:	SOME SIGNIFICANCE: Contributes to the heritage and/or historical development of the locality.
Management Recommendation:	Conservation of the place is desirable. Any proposed change to the place should be in sympathy with the heritage values of the place.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS



Photo Description:

6/11/1996

Suba & Grundy

High pitched roof.