

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 151 Category: 3

 Assessment Date:
 15/10/1996
 Last Revision Date:
 04/11/2009

 HCWA Number:
 13401
 Asset ID:
 MCH126700

PLACE DETAILS

Name: House

Other Names: 111 Fitzgerald Street

Type of Place: House

Address: 111 Fitzgerald Street

Suburb: Geraldton

LOCATION

Map 14.14 GPS 6813919.00 GPS 266461.000

Reference: Northing: 0000 Easting: 000



Photo Description:

6/12/2007 Rod Milne

View from Fitzgerald Street.

Generated: 15/08/2019 Page 1 of 4

SITE DETAILS

Lot No.: Lot 14

Reserv No.: Assess No.: 11142

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

DESCRIPTION

Walls: Weatherboard Roof: Corrugated Iron

Condition: Good Integrity:

Original fabric:

Modifications: Verandah enclosure to north.

This weatherboard house has a steeply pitched hipped corrugated iron roof with a lean-to roof to the rear. A separate hipped verandah roof runs along the street (west) and north sides, supported on timber posts. There is a brick chimney to the south east. The rear yard has a privy with a curved corrugated iron roof. A timber picket fence forms the front property boundary.

HISTORY

Construction Date: unknown Source:

Architect: Unknown Builder: Unknown

No History Available.

HISTORIC THEMES

HCWA: 104 Land allocation and subdivision

303 Mining (including mineral processing)

AHC: 4.1.2 Making suburbs

Generated: 15/08/2019 Page 2 of 4

STATEMENT OF SIGNIFICANCE

This house has aesthetic appeal and enhances the streetscape of the area given its ssimple tyle and retention of original elements such as the corbelled brick chimney and the high pitched roof form.

MANAGEMENT CATEGORY

Management Category: 3

Level of Significance: MODERATE SIGNIFICANCE: Important to the

heritage of the locality.

ManagementConservation of the place is recommended.Recommendation:Any proposed change to the place should not

unduly impact on the heritage values of the place and should retain significant fabric

wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS

Generated: 15/08/2019 Page 3 of 4



Photo Description: 15/10/1996 Suba & Grundy Verandah partly enclosed.

Generated: 15/08/2019 Page 4 of 4