

Area: Geraldton	Place Number: 153	Category: 3
Assessment Date: 15/10/1996	Last Revision Date: 04/11/2009	
HCWA Number: 13403	Asset ID: MCH126703	

PLACE DETAILS

Name:	House
Other Names:	116 Fitzgerald Street
Type of Place:	House
Address:	116 Fitzgerald Street
Suburb:	Beachlands

LOCATION

Map Reference: 14.14	GPS Northing: 6813878.00	GPS Easting: 266395.000
	0000	000



Photo Description:

3/12/2007

Rod Milne

Large brick extension to rear.

SITE DETAILS

Lot No.:	Lot 2	Assess No.:	11084
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Stone/Brick	Roof:	Corrugated Iron
Condition:	Good	Integrity:	
Original fabric:			
Modifications:	Large extension to rear		

The original front section of this stone and brick house has a gambrel roof with a central flying gable to the street (east) facade with a finial and pendant. Surrounding the gable, a bullnose verandah is supported on turned timber posts. The stone work to the original section is finely pointed with red brick quoining and arches to the openings and matching brick quoining to the corners. Windows to the front section are timber framed and casement style with a transom light. A tall brick chimney is situated to the south of the front section. To the rear, a large brick extension has a gable roof with a finial and weatherboard infill to the gable end. The house is separated from the street by a tall limestone block wall.

HISTORY

Construction Date:	unknown	Source:	
Architect:	Unknown		
Builder:	Unknown		

No History Available.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
--------------	-------------------------------------

STATEMENT OF SIGNIFICANCE

Although set behind a limestone wall, this house has many decorative elements such as the pointed stonework with brick quoining, turned timber verandah posts, flying gable and bullnose verandah which are easily viewed from the street. Given this, the place has aesthetic appeal and makes a positive contribution to the streetscape of the area.

MANAGEMENT CATEGORY

Management Category: 3
Level of Significance: MODERATE SIGNIFICANCE: Important to the heritage of the locality.
Management Recommendation: Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS



Photo Description:

15/10/1996

Suba & Grundy

House set behind tall limestone block wall.