

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 178 Category: 2

 Assessment Date:
 14/10/1996
 Last Revision Date:
 19/11/2009

 HCWA Number:
 13275
 Asset ID:
 MCH126846

PLACE DETAILS

Name: Office

Other Names: 18 Francis Street

Type of Place: Office

Address: 18 Francis Street

Suburb: Geraldton

LOCATION

Map 14.15 GPS 6814238.00 GPS 266044.000

Reference: Northing: 0000 Easting: 000



Photo Description:

16/01/2008 Rod Milne

Large former house set in spacious grounds.

Generated: 13/12/2018 Page 1 of 4

SITE DETAILS

Lot No.: Lot 1

Reserv No.: Assess No.: 20382

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Residence

Current Use: Office Ownership:

Public Access: No Occupied: Occupied

DESCRIPTION

Walls: Rendered Masonry Roof: Corrugated Iron

Condition: Not applicable Integrity:

Original fabric:

Modifications: One chimney removed

This large rendered masonry house has a corrugated iron gambrel roof with arched bargeboards to the two timber louvered gablets. A smaller separate gambrel roof to the south east replicates the main roof. A separate hipped verandah roof to the north and east elevation is supported on metal verandah posts. There are two tall rendered masonry chimneys (formerly three) with exposed brick corbelling and terracotta chimney pots to the north east and north west of the main roof. Windows are timber framed and double hung with a french door to the east verandah.

HISTORY

Construction Date: 1890 **Source:** C. Norris

Architect: Unknown Builder: Unknown

Built to house the Geraldton police inspector around the c1890s, this was the residence of Police Inspector Simpson at one time. (Sources: M. Cobley & Norris, C., "Memories of Champion Bay or Old Geraldton", p79)

Generated: 13/12/2018 Page 2 of 4

HISTORIC THEMES

HCWA: 104 Land allocation and subdivision

403 Law and order

AHC: 4.1.2 Making suburbs

7.6.3 Policing Australia

STATEMENT OF SIGNIFICANCE

This former house, now office, has considerable aesthetic significance given its large scale, high integrity and built features such as the tall corbelled chimneys, unusual gablets, timber windows and wrap around verandah. The place makes an important contribution to the built environment of the locale.

MANAGEMENT CATEGORY

Management Category: 2

Level of Significance: CONSIDERABLE SIGNIFICANCE: Very important

to the heritage of the locality.

Management Conservation of the place is highly

Recommendation: recommended. Any proposed change should

not unduly impact on the heritage values of the

place and should retain significant fabric

wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

Norris, C., "Memories of Champion Bay or Old Geraldton", Soroptimist International, 1989.

OTHER PHOTOS

Generated: 13/12/2018 Page 3 of 4



Photo Description: 14/10/1996 Suba & Grundy Chimney to left since removed.

Generated: 13/12/2018 Page 4 of 4