

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

| Area: | Geraldton | Place Numbe | r: 198 | Categor | y: 4 |
|--------|------------|------------------|---------------|---------|-------------|
| Assess | ment Date: | 15/10/1996 La | st Revision | Date: 2 | 24/11/2009 |
| HCWA | Number: | 13295 A s | set ID: | ٨ | MCH126942 |

PLACE DETAILS

| Name: | House |
|----------------|-------------------|
| Other Names: | 96 Francis Street |
| Type of Place: | House |
| Address: | 96 Francis Street |
| Suburb: | Beachlands |

LOCATION

| Мар | 14.14 | GPS | 6813599.00 | GPS | 266120.000 |
|------------|-------|-----------|------------|----------|------------|
| Reference: | | Northing: | 0000 | Easting: | 000 |



Photo Description: 31/10/2007 Rod Milne Verandah removed from front facade.

SITE DETAILS

| Lot No.: | Lot 4 | | |
|--------------------------|-------|-------------------------|------|
| Reserv No.: Dia/Plan: | | Assess No.: Vol/Fol: | 7190 |

USE OF PLACE

| Original Use: Current Use: | Residence Residence | | |
|-------------------------------|------------------------|-----------|----------|
| Ownership: Public Access: | Νο | Occupied | Occupied |
| FUDIIC ACCESS: | INU | Occupied: | Occupied |

DESCRIPTION

| Walls: Condition: | Rendered Masonry Good | Roof: Integrity: | Asbestos |
|--|--------------------------|---------------------|----------|
| Original fabric Modifications: | | | |
| This house, which fronts on to the footpath, has rendered masonry exterior walls with a hipped asbestos roof and a lean-to roof to the rear which covers a fibro clad extension. There are two chimneys to the main roof symmetrically placed to the south and north. There is no verandah to the | | | |

front but a corrugated iron awning covers the window to the north facade. Original windows have been replaced with aluminium frames. There is a low rendered masonry wall to the street frontage.

| HISTORY | | | |
|--|-------------------------------|---------|--|
| Construction Date: Architect: Builder: | unknown Unknown Unknown | Source: | |
| No History Available. | | | |

HISTORIC THEMES

| HCWA: | 104 Land allocation and subdivision |
|-------|---|
| AHC: | 4.1.2 Making suburbs |
| | 3.8.6 Building and maintaining railways |

STATEMENT OF SIGNIFICANCE

Although the verandah has been removed, the place retains much of its original form and contibutes to the streetscape of the area.

MANAGEMENT CATEGORY

| Management Category: Level of Significance: | 4 SOME SIGNIFICANCE: Contributes to the heritage and/or historical development of the locality. |
|--|---|
| Management Recommendation: | Conservation of the place is desirable. Any proposed change to the place should be in sympathy with the heritage values of the place. |

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

Bibliography: Considine & Griffiths, "Walkaway Railway Station Precinct Conservation Plan", 1996. HCWA Database No. 13882.

OTHER PHOTOS



Photo Description: 15/10/1996 Suba & Grundy Symmetrical facade.