

<b>Area:</b> Geraldton	<b>Place Number:</b> 199	<b>Category:</b> 6
<b>Assessment Date:</b> 05/11/1996	<b>Last Revision Date:</b> 24/11/2009	
<b>HCWA Number:</b> 13296	<b>Asset ID:</b> MCH126946	

### PLACE DETAILS

<b>Name:</b>	Site
<b>Other Names:</b>	79 George Road
<b>Type of Place:</b>	Site
<b>Address:</b>	79 George Road
<b>Suburb:</b>	Geraldton

### LOCATION

<b>Map Reference:</b> 15.15	<b>GPS Northing:</b> 6815386.00	<b>GPS Easting:</b> 267348.000
	<b>GPS Easting:</b> 0000	<b>GPS Northing:</b> 000



**Photo Description:**

5/11/1996  
Suba & Grundy  
East elevation.

## SITE DETAILS

<b>Lot No.:</b>	Lot 16	<b>Assess No.:</b>	12647
<b>Reserv No.:</b>		<b>Vol/Fol:</b>	
<b>Dia/Plan:</b>			

## USE OF PLACE

<b>Original Use:</b>	Residence		
<b>Current Use:</b>	Residence		
<b>Ownership:</b>			
<b>Public Access:</b>	No	<b>Occupied:</b>	Occupied

## DESCRIPTION

<b>Walls:</b>	Brick/Fibro	<b>Roof:</b>	Corrugated Iron
<b>Condition:</b>	Good	<b>Integrity:</b>	
<b>Original fabric:</b>			
<b>Modifications:</b>			

This house has been demolished. The following description is from the 1997 Municipal Inventory: This brick house has a steeply pitched corrugated iron gambrel roof which extends to cover the surrounding verandahs. The verandahs are enclosed to the corners and sides with fibro and are supported to the front on metal poles with a masonry balustrade. The face brick is pointed and the front facade features a centrally placed recessed entry porch with a rendered masonry arch with timber framed awning windows to each side. Windows to the front verandah are timber framed and casement style.

## HISTORY

<b>Construction Date:</b>	unknown	<b>Source:</b>	Owner Knowledge
<b>Architect:</b>	Unknown		
<b>Builder:</b>	Unknown		

No History Available.

## HISTORIC THEMES

<b>HCWA:</b>	104 Land allocation and subdivision 301 Grazing, pastoralism and dairying
--------------	--

**AHC:** 605 Famous and infamous people  
4.1.2 Making suburbs

### STATEMENT OF SIGNIFICANCE

This house had had some alterations but much of its original fabric and style was still evident.  
1997 Management Category: 6. SIGNIFICANT, BUT DIMINISHED. Assess in more detail when considering a development application.

### MANAGEMENT CATEGORY

**Management Category:** 6  
**Level of Significance:** MUNICIPAL INVENTORY ARCHIVE: Place was previously included in the Municipal Inventory but has been removed due to demolition or diminished heritage significance.  
**Management Recommendation:** The place does not form part of the relevant local Town Planning Scheme Heritage List. This category is for record keeping purposes only.

### OTHER LISTINGS

No other listings

### SUPPORTING INFORMATION

Bibliography:  
Suba, T., "The Greenough Front Flats Bibliography of Local Sources and Table of Heritage Places", 1994.  
HCWA Database No. 13883.

### OTHER PHOTOS

No other photos