

# City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 3 Category: 3

 Assessment Date:
 15/10/1996
 Last Revision Date:
 19/06/2009

 HCWA Number:
 13196
 Asset ID:
 MCH126879

# **PLACE DETAILS**

Name: House

Other Names: 113 Augustus Street

**Type of Place:** House

Address: 113 Augustus Street

**Suburb:** Geraldton

# **LOCATION**

 Map
 14.14
 GPS
 6814075.00
 GPS
 266473.000

 Reference:
 Northing:
 0000
 Easting:
 000



## **Photo Description:**

23/07/2007 Rod Milne

View of the house from the street.

Generated: 15/08/2019 Page 1 of 4

## SITE DETAILS

Lot No.: Lot 4

Reserv No.: Assess No.: 10344

Dia/Plan: Vol/Fol:

# **USE OF PLACE**

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

## **DESCRIPTION**

Walls: Corrugated Iron Roof: Corrugated Iron

**Condition:** Good **Integrity:** 

Original fabric:

**Modifications:** Verandah balustrade infill

This small cottage has a brown painted corrugated iron gable roof which extends to cover the front verandah. There is also a large lean-to roof to the rear. The verandah roof is hipped to each end and is supported on timber posts which have decorative braces and a scalloped valance below the gutter. A timber handrail runs between the verandah posts with fibro sheet infill below. The cottage is clad with vertically placed corrugated iron sheets which are painted cream and blue. Windows to the front elevation are 12 pane double hung timber framed and symmetrically placed each side of the central entry door. Windows to the side have a small corrugated iron awning.

#### HISTORY

**Construction Date:** unknown **Source:** Feilman

Architect: Unknown Builder: Unknown

No History Available.

## HISTORIC THEMES

**HCWA:** 104 Land allocation and subdivision

Generated: 15/08/2019 Page 2 of 4

401 Government and politics 603 Local heroes and battlers

**AHC:** 4.1.2 Making suburbs

# STATEMENT OF SIGNIFICANCE

The house has considerable aesthetic charm given its simple style, small scale and use of construction materials. Further the place has rarity value as one of only a few houses of corrugated iron construction remaining in the town. The place makes a positive contribution to the streetscape which, combined with its high integrity and the decorative verandah treatment, add to the significance of the place.

## MANAGEMENT CATEGORY

Management Category: 3

**Level of Significance:** MODERATE SIGNIFICANCE: Important to the

heritage of the locality.

ManagementConservation of the place is recommended.Recommendation:Any proposed change to the place should not

unduly impact on the heritage values of the place and should retain significant fabric

wherever feasible.

## OTHER LISTINGS

Shire of Greenough - Town Planning Scheme (11), 01/01/1970 National Trust of WA - Recorded, 01/01/1970

## SUPPORTING INFORMATION

Bibliography:

Feilman, M., "Greenough Historical Survey of the Front Flats",1977 (11). Suba, T., "The Greenough Front Flats Bibliography of Local Sources and Table of Heritage Places", 1994.

HCWA Database No. 13988.

### OTHER PHOTOS

Generated: 15/08/2019 Page 3 of 4



Photo Description: 15/10/1996 Suba & Grundy The north elevation.

Generated: 15/08/2019 Page 4 of 4