

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 215 Category: 2

 Assessment Date:
 14/10/1996
 Last Revision Date:
 25/11/2009

 HCWA Number:
 13310
 Asset ID:
 MCH126986

PLACE DETAILS

Name: House

Other Names: 49-51 Gregory Street

Type of Place: House

Address: 49-51 Gregory Street

Suburb: Geraldton

LOCATION

 Map
 14.15
 GPS
 6814232.00
 GPS
 266284.000

 Reference:
 Northing:
 0000
 Easting:
 000



Photo Description:

13/04/2008 Tanya Henkel View showing steeply pitched roof.

Generated: 13/12/2018 Page 1 of 4

SITE DETAILS

Lot No.: Lot 210

Reserv No.: Assess No.: 11569

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

DESCRIPTION

Walls: Stone (Rendered) Roof: Corrugated Iron

Condition: Good Integrity:

Original fabric: Modifications:

This long limestone rubble building fronts directly on to the street. There is a steeply pitched corrugated iron gable roof which extends to the front (west) to cover the verandah and also extends as a shallow pitch skillion roof to the rear. The stone has been rendered to the front and north facades. The verandahs are supported on half timber posts and enclosed with lattice above a masonry balustrade. There are two separate wrought iron entry gates to the street. Windows are timber framed and double hung, 18 pane. A single chimney is centrally placed to the apex of the gable.

HISTORY

Construction Date: 1876 **Source:** Feilman

Architect: Unknown Unknown

Contact the owner for historical information.

HISTORIC THEMES

HCWA: 104 Land allocation and subdivision

602 Early settlers

Generated: 13/12/2018 Page 2 of 4

AHC: 4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

These two semi-detached cottages have historic significance for their connection to the early development of Geraldton and as evidence of early forms of housing in the town. The place adds considerably to the streetscape of the locale given its use of local materials, steep roof pitch and full length verandah.

MANAGEMENT CATEGORY

Management Category: 2

Level of Significance: CONSIDERABLE SIGNIFICANCE: Very important

to the heritage of the locality.

Management Conservation of the place is highly

Recommendation: recommended. Any proposed change should

not unduly impact on the heritage values of the

place and should retain significant fabric

wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

Feilman & Associates, "Survey of Places of Historic and Landscape Significance in Geraldton", 1977.

OTHER PHOTOS

Generated: 13/12/2018 Page 3 of 4



Photo Description:

8/03/2007 Rod Milne



Photo Description:

14/10/1996
Suba & Grundy
Building fronts directly onto footpath.

Generated: 13/12/2018

Page 4 of 4