

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Gerald	ton Place	Number: 218	Category:	2
Assessment Do	i te: 14/10/1996	Last Revision	Date: 25/1	1/2009
HCWA Numbe	r: 13313	Asset ID:	MC	H127020

PLACE DETAILS

Name:	House
Other Names:	53 Gregory Street
Type of Place:	House
Address:	53 Gregory Street
Suburb:	Geraldton

LOCATION

Мар	14.14	GPS	6814214.00	GPS	266305.000
Reference:		Northing:	0000	Easting:	000



Photo Description: 14/11/2007 Rod Milne Front facade showing verandah decoration.

SITE DETAILS

Lot No.:	Lot 211		
Reserv No.:	Railway Reserve	Assess No.:	11570
Dia/Plan:		Vol/Fol:	

USE OF PLACE			
Original Use: Current Use:	Residence Residence		
Ownership:		O a cursia du	
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls: Condition: Original fabric Modifications		Roof: Integrity:	Zincalume
zincalume roo (west) verand verandah roo verandah frie facade has fo and rendered facade are e the side wind	of with a separ dah. Half timbe of. The posts he ze and there is ace red brickw d below. The tw enhanced by d ows. The side all lean-to to th	s directly on to the stree ate shallow pitched hip er posts on rendered brid ave decorative bracket s a red brick balustrade vork which is tuckpointed win double hung timber lecorative rendering wit of the building has beer e rear and a corbelled b	ped roof to the front ck piers support the s to a scalloped below. The front d to window sill height windows to the street h arched brickwork to n cement washed and

HISTORY			
Construction Date: Architect: Builder:	1890 Unknown Unknown	Source:	Feilman
No History Available.			

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
	202 Rail and light rail transport
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

This brick house has high aesthetic significance given that much of its original fabric remains intact including the decorative elements to the verandah and as such is a good representation of brick houses of its era. The place makes a high contribution to the streetscape of the area.

MANAGEMENT CATEGORY

Management Category: Level of Significance:	2 CONSIDERABLE SIGNIFICANCE: Very important to the heritage of the locality.
Management Recommendation:	Conservation of the place is highly recommended. Any proposed change should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

Australian Heritage Commission - Register, 01/01/1970

SUPPORTING INFORMATION

Feilman & Associates, "Survey of Places of Historic and Landscape Significance in Geraldton", 1977.

OTHER PHOTOS



Photo Description: 14/10/1996 Suba & Grundy House fronts directly onto footpath.