

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 250 Category: 4

 Assessment Date:
 06/11/1996
 Last Revision Date:
 27/11/2009

 HCWA Number:
 13420
 Asset ID:
 MCH126603

PLACE DETAILS

Name: House

Other Names: 17 Henry Street

Type of Place: House

Address: 17 Henry Street

Suburb: Beresford

LOCATION

 Map
 15.17
 GPS
 6816712.00
 GPS
 267372.000

 Reference:
 Northing:
 0000
 Easting:
 000



Photo Description:

26/06/2009 Tanya Henkel Roof changes with adjoining carport.

Generated: 15/08/2019 Page 1 of 4

SITE DETAILS

Lot No.: Lot 1

Reserv No.: Assess No.: 14205

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

DESCRIPTION

Walls: Weatherboard/Fibro Roof: Corrugated Iron

Condition: Good Integrity:

Original fabric:

Modifications: Carport to side

This small timber framed weatherboard and corrugated iron clad house is set well back from the street. The place has a gambrel corrugated iron roof which extends to cover the front verandah roof to the east elevation while there is a skillion roof to the rear. The verandah is supported on timber posts. The front roof has been modified to include a gable. Windows are timber framed with a mixture of awning and casement styles. A brick chimney is sited to the rear of the main roof.

HISTORY

Construction Date: unknown Source:

Architect: Unknown Unknown

No History Available.

HISTORIC THEMES

HCWA: 104 Land allocation and subdivision

AHC: 4.1.2 Making suburbs

Generated: 15/08/2019 Page 2 of 4

STATEMENT OF SIGNIFICANCE

This small house retains much of its original simple style and character and as such is representative of its era. Further the place contributes to the built fabric of the locale. Together with the adjacent house, 15 Henry Street, this place is unusual for the area given its setback from the road, construction materials, small scale and simple style.

MANAGEMENT CATEGORY

Management Category: 4

Level of Significance: SOME SIGNIFICANCE: Contributes to the

heritage and/or historical development of the

locality.

Management Conservation of the place is desirable. Any **Recommendation:** proposed change to the place should be in

sympathy with the heritage values of the place.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS

Generated: 15/08/2019 Page 3 of 4



Photo Description: 6/11/1996 Suba & Grundy Set in an elevated position.

Generated: 15/08/2019 Page 4 of 4