

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 251 Category: 4

 Assessment Date:
 05/11/1996
 Last Revision Date:
 27/11/2009

 HCWA Number:
 13421
 Asset ID:
 MCH126609

PLACE DETAILS

Name: House

Other Names: 7 Hermitage Street

Type of Place: House

Address: 7 Hermitage Street

Suburb: Geraldton

LOCATION

Map 15.14 GPS 6813500.00 GPS 267353.000

Reference: Northing: 0000 Easting: 000



Photo Description:

31/10/2007 Rod Milne Set behind a picket fence.

Generated: 15/08/2019 Page 1 of 4

SITE DETAILS

Lot No.: Lot 5

Reserv No.: Assess No.: 11270

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

DESCRIPTION

Walls: Weatherboard/Fibro Roof: Corrugated Iron

Condition: Good Integrity:

Original fabric: Modifications:

This timber framed house has a combination gable and hipped roof with a lean-to roof to the rear. The main roof has a broken back extension to the front verandah which is supported on turned timber posts. There is weatherboard cladding to window sill height with fibro above. Windows are a mixture of timber framed casement and double hung styles. There is a picket fence to the street boundary.

HISTORY

Construction Date: unknown Source:

Architect: Unknown Builder: Unknown

No History Available.

HISTORIC THEMES

HCWA: 104 Land allocation and subdivision

AHC: 4.1.2 Making suburbs

Generated: 15/08/2019 Page 2 of 4

STATEMENT OF SIGNIFICANCE

This small house, although altered, still retains most of the original fabric and decorative elements such as the turned timber posts. The place enhances the streetscape of the locale given its small scale, simple style and use of construction materials.

MANAGEMENT CATEGORY

Management Category: 4

Level of Significance: SOME SIGNIFICANCE: Contributes to the

heritage and/or historical development of the

locality.

Management Conservation of the place is desirable. Any **Recommendation:** proposed change to the place should be in

sympathy with the heritage values of the place.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS

Generated: 15/08/2019 Page 3 of 4



Photo Description: 5/11/1996

Suba & Grundy
Broken back verandah roof.

Generated: 15/08/2019

Page 4 of 4