

# City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 256 Category: 4

 Assessment Date:
 25/10/1996
 Last Revision Date:
 27/11/2009

 HCWA Number:
 13426
 Asset ID:
 MCH126629

## **PLACE DETAILS**

Name: House

Other Names: 9 Jose Street

**Type of Place:** House

Address: 9 Jose Street Suburb: Beachlands

## **LOCATION**

Map 14.14 GPS 6813791.00 GPS 265859.000

Reference: Northing: 0000 Easting: 000



## **Photo Description:**

13/11/2007

Rod Milne

Weatherboard house set behind picket fence.

Generated: 15/08/2019 Page 1 of 4

## **SITE DETAILS**

**Lot No.:** Lot 482

Reserv No.: Assess No.: 10405

Dia/Plan: Vol/Fol:

## **USE OF PLACE**

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

#### **DESCRIPTION**

Walls: Weatherboard Roof: Tile

**Condition:** Fair **Integrity:** 

Original fabric:

**Modifications:** Numerous changes over time

This timber framed weatherboard clad house has a tiled hipped roof with a separate gable roof to the front (main) room. The roof extends to cover the verandah which is supported on timber posts with a simple timber balustrade. The gable end has fibro and timber batten infill and below it a tiled awning covers the window to the main room. Windows are eight paned timber framed casement style. The street boundary has a Gothic style timber picket fence and the street verge features two large Norfolk Island Pines (Araucaria heterophylla).

#### **HISTORY**

**Construction Date:** unknown **Source:** S. Gratte

Architect: Unknown Builder: Unknown

No History Available.

#### HISTORIC THEMES

**HCWA:** 104 Land allocation and subdivision

308 Commercial services and industries

**AHC:** 4.1.2 Making suburbs

Generated: 15/08/2019 Page 2 of 4

## STATEMENT OF SIGNIFICANCE

This simple weatherboard house has had some alterations but retains much of its original fabric and style and as such enhances the streetscape of the area.

## MANAGEMENT CATEGORY

Management Category: 4

**Level of Significance:** SOME SIGNIFICANCE: Contributes to the

heritage and/or historical development of the

locality.

**Management** Conservation of the place is desirable. Any **Recommendation:** proposed change to the place should be in

sympathy with the heritage values of the place.

# **OTHER LISTINGS**

No other listings

#### SUPPORTING INFORMATION

### **OTHER PHOTOS**

Generated: 15/08/2019 Page 3 of 4



Photo Description: 25/10/1996 Suba & Grundy Timber batten infill to gable end.

Generated: 15/08/2019 Page 4 of 4