

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 258 Category: 4

 Assessment Date:
 25/10/1996
 Last Revision Date:
 27/11/2009

 HCWA Number:
 13428
 Asset ID:
 MCH126632

PLACE DETAILS

Name: House

Other Names: 13 Jose Street

Type of Place: House

Address: 13 Jose Street Beachlands

LOCATION

Map 14.14 GPS 6813788.00 GPS 265812.000

Reference: Northing: 0000 Easting: 000



Photo Description:

13/11/2009 Rod Milne

House set behind high brick wall.

Generated: 15/08/2019 Page 1 of 4

SITE DETAILS

Lot No.: Lot 1

Reserv No.: Assess No.: 10402

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

DESCRIPTION

Walls: Brick (Rendered) Roof: Corrugated Iron

Condition: Good Integrity:

Original fabric: Modifications:

This stucco rendered house is situated behind a high brick wall. A hipped roof has gables to the side and front main room. The front gable end has roughcast and timber infill. The main roof extends to cover a front verandah which is supported on timber posts. Windows are eight pane timber framed and casement style.

HISTORY

Construction Date: unknown Source:

Architect: Unknown Builder: Unknown

No History Available.

HISTORIC THEMES

HCWA: 104 Land allocation and subdivision

308 Commercial services and industries

AHC: 4.1.2 Making suburbs

Generated: 15/08/2019 Page 2 of 4

STATEMENT OF SIGNIFICANCE

Although sited behind a tall brick wall the place nevertheless enhances the streetscape of Jose Street given the high-pitched roof structure which is clad with short sheets of corrugated iron, the decorative gable and awning supports which are evident from the street.

MANAGEMENT CATEGORY

Management Category: 4

Level of Significance: SOME SIGNIFICANCE: Contributes to the

heritage and/or historical development of the

locality.

Management Conservation of the place is desirable. Any **Recommendation:** proposed change to the place should be in

sympathy with the heritage values of the place.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS

Generated: 15/08/2019 Page 3 of 4



Photo Description: 25/10/1996 Suba & Grundy Roof form and decorative detailing evident.

Generated: 15/08/2019 Page 4 of 4