

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 324 Category: 5

 Assessment Date:
 06/11/1996
 Last Revision Date:
 10/03/2010

 HCWA Number:
 13718
 Asset ID:
 MCH126697

PLACE DETAILS

Name: House

Other Names: 72 Mitchell Street

Type of Place: House

Address: 72 Mitchell Street

Suburb: Spalding

LOCATION

Map 16.19 **GPS** 6818289.00 **GPS** 268546.000

Reference: Northing: 0000 Easting: 000



Photo Description:

22/08/2007 Rod Milne View from Mitchell Street.

Generated: 15/08/2019 Page 1 of 4

SITE DETAILS

Lot No.: Lot 1

Reserv No.: Assess No.: 13390

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

DESCRIPTION

Walls: Fibro/weathboard Roof: Corrugated Iron

Condition: Good Integrity:

Original fabric: Modifications:

This timber framed fibro and weatherboard clad house has a corrugated iron gable roof with a separate gable to the front (north). The gable end has fibro and timber batten infill and below the gable end a separate verandah roof is supported on timber posts. Windows are casement style and there is a large palm (phoenix canariensis) to the north west corner of the front garden.

HISTORY

Construction Date: unknown **Source:** Feilman

Architect: Unknown Builder: Unknown

No History Available.

HISTORIC THEMES

HCWA: 104 Land allocation and subdivision

AHC: 4.1.2 Making suburbs

Generated: 15/08/2019 Page 2 of 4

STATEMENT OF SIGNIFICANCE

This house is of simple style and appears to be of different style and age to other housing in this locality.

MANAGEMENT CATEGORY

Management Category: 5

Level of Significance: HISTORIC SITE: The site has historic significance

for its previous use and its role in the historical

development of the locality.

Management Recommendation:

Proposed development may need to have regard to possible archaeological evidence

remaining on the site. Recognise and interpret

the site if feasible. This may be achieved

through a variety of methods including, but not limited to, signage, public art, paving treatment and landscaping as well as design treatment of

any new development which reflects the

former use of the site.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

Feilman & Associates, "Survey of Places of Historic and Landscape Significance in Geraldton", 1977.

OTHER PHOTOS

Generated: 15/08/2019 Page 3 of 4



Photo Description: 6/11/1996 Suba & Grundy View from Mitchell Street.

Generated: 15/08/2019 Page 4 of 4