

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 325 Category: 2

 Assessment Date:
 06/11/1996
 Last Revision Date:
 10/03/2010

 HCWA Number:
 13719
 Asset ID:
 MCH126701

PLACE DETAILS

Name: 1st Bluff Point Scouts Hall, Fmr

Other Names: 8 Morris Street

Type of Place: Hall

Address: 8 Morris Street Suburb: 8 Inft Point

LOCATION

Map 15.18 GPS 6817849.00 GPS 267488.000

Reference: Northing: 0000 Easting: 000



Photo Description:

1/08/2007 Rod Milne Simple timber framed halls.

Generated: 13/12/2018 Page 1 of 4

SITE DETAILS

Lot No.: Lot 1725

Reserv No.: 26777 **Assess No.:** 11860

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Scout Hall
Current Use: Men's Club

Ownership: Scout Association of Australia

Public Access: No Occupied: Occupied

DESCRIPTION

Walls: Weatherboard/Fibro Roof: Asbestos

Condition: Fair **Integrity:**

Original fabric:

Modifications: Original roofing replaced

There are two timber framed fibro clad buildings set at right angles to each other with the larger building running north-south. Both buildings have a gable fibro roof with fibro cladding to the upper half of the walls and weatherboard below. The larger building has aluminium framed windows, the smaller has timber framed casement windows.

HISTORY

Construction Date: 1940 Source:

Architect: Unknown Builder: Unknown

The building was originally located at the Geraldton Air Port. (Source: B. Shields) The design and construction of the buildings is typical of buildings constructed for the RAAF during the Second World War, with Geraldton being a notable air base during that time.

HISTORIC THEMES

HCWA: 501 World wars and other wars

405 Sport, recreation and entertainment

AHC: 7.7 Defending Australia

Generated: 13/12/2018 Page 2 of 4

STATEMENT OF SIGNIFICANCE

These small halls have social significance for their association with RAAF operations in the Geraldton area during the Second World War and later with the Scout movement in Bluff Point for many years. The place is evidence of how buildings can be relocated for reuse.

MANAGEMENT CATEGORY

Management Category: 2

Level of Significance: CONSIDERABLE SIGNIFICANCE: Very important

to the heritage of the locality.

Management Conservation of the place is highly

Recommendation: recommended. Any proposed change should

not unduly impact on the heritage values of the

place and should retain significant fabric

wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS

Generated: 13/12/2018 Page 3 of 4



Photo Description: 6/11/1996 Suba & Grundy One of two halls on site.

Generated: 13/12/2018 Page 4 of 4