

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 329 Category: 2

 Assessment Date:
 06/11/1996
 Last Revision Date:
 10/03/2010

 HCWA Number:
 13722
 Asset ID:
 MCH126714

PLACE DETAILS

Name: House

Other Names: 6 Nichols Street

Type of Place: House

Address: 6 Nichols Street

Suburb: Beresford

LOCATION

 Map
 15.18
 GPS
 6817581.00
 GPS
 267822.000

 Reference:
 Northing:
 0000
 Easting:
 000



Photo Description:

31/07/2007 Rod Milne

Front facade from Nichols Street.

Generated: 13/12/2018 Page 1 of 4

SITE DETAILS

Lot No.: Lot 101

Reserv No.: Assess No.: 20297

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

DESCRIPTION

Walls: Brick/Stucco Roof: Corrugated Iron

Condition: Good Integrity:

Original fabric: Modifications:

This brick house has a corrugated iron gambrel roof with a separate gable roof to the north. The main roof extends to cover the surrounding verandahs which are supported on timber posts with brackets to the verandah beam. The verandah to the south west corner is partly enclosed with trellis. The walls are stucco rendered above window ledge height with red face tuckpointed brick below. Windows are timber framed and casement style. To the rear there are two tall stucco rendered brick chimneys. A picket fence forms the front boundary while a corrugated iron clad garage is sited to the north west corner of the block. (See also 4 Nichols Street.)

HISTORY

Construction Date: 1930 Source:

Architect: Unknown Builder: Unknown

This house, and the adjacent 4 Nichols Street, were built for the manager and accountant of Cummings Smith and Mt Lyle Super Works. (Source:

Shirley Scotter)

Generated: 13/12/2018 Page 2 of 4

HISTORIC THEMES

HCWA: 104 Land allocation and subdivision

AHC: 4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

The house has historic significance for its connection to the development of the superphosphate industry in Geraldton. The place has high aesthetic significance given its setting, integrity and condition and makes a high contribution to the street scape. The house is one of a pair which has similar characteristics and development proposals should be considered in that context.

MANAGEMENT CATEGORY

Management Category: 2

Level of Significance: CONSIDERABLE SIGNIFICANCE: Very important

to the heritage of the locality.

Management Conservation of the place is highly

Recommendation: recommended. Any proposed change should

not unduly impact on the heritage values of the

place and should retain significant fabric

wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS

Generated: 13/12/2018 Page 3 of 4



Photo Description:

6/11/1996 Suba & Grundy Tall chimneys punctuate the roofscape.

Generated: 13/12/2018 Page 4 of 4