

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 350 Category: 3

 Assessment Date:
 08/12/1996
 Last Revision Date:
 11/03/2010

 HCWA Number:
 13742
 Asset ID:
 MCH126847

PLACE DETAILS

Name: Concrete Steps

Other Names: Queens Park, Sanford Street

Type of Place: Steps

Address: Queens Park, Sanford Street

Suburb: Geraldton

LOCATION

Map 15.15 **GPS** 6814504.00 **GPS** 266940.000

Reference: Northing: 0000 Easting: 000



Photo Description:

28/08/2007 Rod Milne Steep concrete steps.

Generated: 13/12/2018 Page 1 of 4

SITE DETAILS

Lot No.: Lot 550

Reserv No.: 30845 **Assess No.:** 11674

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Steps
Current Use: Steps

Ownership: City of Geraldton-Greenough

Public Access: Yes Occupied: Not Occupied

DESCRIPTION

Walls: Concrete Roof: Not applicable

Condition: Good Integrity:

Original fabric: Modifications:

A series of 13 steep concrete steps allows access from Queens Park to the parking area above. The steps have a low rendered masonry balustrade with capped piers to each side which are decorated with graffiti. There is a central metal handrail.

HISTORY

Construction Date: 1927 Source: Stan Gratte

Architect: Unknown Builder: Unknown

It is believed that the steps date from about 1927 when the croquet and tennis courts were developed at the top of the steps. (Source: Stan Gratte - he has a photograph of the steps taken in 1942) Used when sport and other activities such as inter district fire brigade demonstrations took place on the area now known as Queen's Park. (Source: Max Eves)

HISTORIC THEMES

HCWA: 405 Sport, recreation and entertainment

AHC: 8.1.3 Developing public parks and gardens 8.1.1 Playing and watching organised sport

Generated: 13/12/2018

STATEMENT OF SIGNIFICANCE

The steps have historic significance for their connection to the original recreation ground near Queens Park.

MANAGEMENT CATEGORY

Management Category: 3

Level of Significance: MODERATE SIGNIFICANCE: Important to the

heritage of the locality.

ManagementConservation of the place is recommended.Recommendation:Any proposed change to the place should not

unduly impact on the heritage values of the place and should retain significant fabric

wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS

Generated: 13/12/2018 Page 3 of 4



Photo Description: 8/12/1996 Suba & Grundy Low rendered masonry balustrade and central metal handrail.

Generated: 13/12/2018 Page 4 of 4