

City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 374 Category: 4

 Assessment Date:
 24/10/1996
 Last Revision Date:
 15/03/2010

 HCWA Number:
 13768
 Asset ID:
 MCH126580

PLACE DETAILS

Name: House

Other Names: 178 Shenton Street

Type of Place: House

Address: 178 Shenton Street

Suburb: Beachlands

LOCATION

Map 14.14 GPS 6813752.00 GPS 265947.000

Reference: Northing: 0000 Easting: 000



Photo Description:

13/11/2007 Rod Milne View of front facade.

Generated: 15/08/2019 Page 1 of 4

SITE DETAILS

Lot No.: Lot 1023

Reserv No.: Assess No.: 10500

Dia/Plan: Vol/Fol:

USE OF PLACE

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

DESCRIPTION

Walls: Brick (Rendered) Roof: Corrugated Iron

Condition: Good Integrity:

Original fabric: Modifications:

This rendered brick house has a gambrel corrugated iron roof with a separate gable to the main room. The gable end is enclosed with fibro with timber battens. The main roof extends to cover a verandah to the side of the gable. Windows have been replaced and are aluminium framed. There is a tall fence with pickets set between brick piers to the street boundary.

HISTORY

Construction Date: unknown Source:

Architect: Unknown Builder: Unknown

No History Available.

HISTORIC THEMES

HCWA: 104 Land allocation and subdivision

AHC: 4.1.2 Making suburbs

Generated: 15/08/2019 Page 2 of 4

STATEMENT OF SIGNIFICANCE

Although it has lost some of its original features, the high-pitched roof and gable end design contributes to the streetscape of the area.

MANAGEMENT CATEGORY

Management Category: 4

Level of Significance: SOME SIGNIFICANCE: Contributes to the

heritage and/or historical development of the

locality.

Management Recommendation:

Conservation of the place is desirable. Any proposed change to the place should be in sympathy with the heritage values of the place.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS

Generated: 15/08/2019 Page 3 of 4



Photo Description: 24/10/1996 Suba & Grundy Original windows replaced.

Generated: 15/08/2019 Page 4 of 4