

# City of Greater Geraldton Municipal Inventory of Heritage Places Place Record

Area: Geraldton Place Number: 382 Category: 4

 Assessment Date:
 06/11/1996
 Last Revision Date:
 15/03/2010

 HCWA Number:
 13776
 Asset ID:
 MCH126606

# **PLACE DETAILS**

Name: House

Other Names: 236 Sixth Street

**Type of Place:** House

Address: 236 Sixth Street Suburb: Wonthella

# **LOCATION**

Map 16.16 GPS 6815583.00 GPS 268492.000

Reference: Northing: 0000 Easting: 000



# **Photo Description:**

12/11/2007 Rod Milne

Corrugated iron clad cottage.

Generated: 15/08/2019 Page 1 of 4

# **SITE DETAILS**

**Lot No.:** Lot 467

Reserv No.: Assess No.: 15226

Dia/Plan: Vol/Fol:

# **USE OF PLACE**

Original Use: Residence Current Use: Residence

Ownership:

Public Access: No Occupied: Occupied

#### **DESCRIPTION**

Walls: Corrugated Iron Roof: Corrugated Iron

Condition: Good Integrity:

Original fabric: Modifications:

This timber framed corrugated iron clad cottage has a steeply pitched corrugated iron gable roof. The rear of the house has a skillion roof and the front gable roof has a broken back extension which covers the front verandah. The verandah is enclosed with corrugated iron.

#### **HISTORY**

**Construction Date:** unknown **Source:** Previous owner

Architect: Unknown Builder: Unknown

No History Available.

### **HISTORIC THEMES**

**HCWA:** 104 Land allocation and subdivision

**AHC:** 4.1.2 Making suburbs

Generated: 15/08/2019 Page 2 of 4

# STATEMENT OF SIGNIFICANCE

This house is of simple style and design with much of its original fabric intact. The place is representative of corrugated iron clad houses of its era of which few remain of high integrity. Further the place adds to the streetscape of the area.

# **MANAGEMENT CATEGORY**

Management Category: 4

**Level of Significance:** SOME SIGNIFICANCE: Contributes to the

heritage and/or historical development of the

locality.

**Management** Conservation of the place is desirable. Any **Recommendation:** proposed change to the place should be in

sympathy with the heritage values of the place.

# **OTHER LISTINGS**

No other listings

# **SUPPORTING INFORMATION**

#### **OTHER PHOTOS**

Generated: 15/08/2019 Page 3 of 4



Photo Description: 6/11/1996 Suba & Grundy Window awnings to side elevation.

Generated: 15/08/2019 Page 4 of 4