

City of Greater Geraldton

Municipal Inventory Place Record

Area: Geraldton Place No: 060 Category: 3X

Assessment Date: 05-Dec-96 HCWA No: 13244 Last revision date: 06-Oct-09

Place Details:

Name: House

Other Names: 206 Chapman Road

Type of Place: House

Address: 206 Chapman Road

Map Reference: 15.16

Suburb: Geraldton Site Area: 0

GPS Northing 6816512 **GPS Easting**: 267289

Photo Description:

10/01/2008 Rod Milne

The front (west) elevation of the house with

picket fence.

Site Details:

Lot / Location: Lot 72 Diagram/Plan:

Reserve: Vol/Folio:

Assess No: 6019 Purpose:

Occupied: Vesting:

Public Access: No Occupier:

Lease:

Wednesday, 27 January 2016

Name: House

Asset ID: G060



City of Greater Geraldton

Municipal Inventory Place Record

Uses of Place:			
Original Use:	Residence	Current Use:	Residence
Description:			
Walls:	Weatherboard	Roof:	Tile
Condition:	Good	Integrity:	
Original Fabric:		Modifications:	Roof replaced with tiles.
This building is a timber framed weatherboard clad house with a hipped tiled roof which extends broken-back to cover the front verandah. There is a separate small gable with weatherboard to the gable end above the verandah which enhances the main entrance. The verandah is supported on timber posts with fibro infill below the handrail. There are two rendered chimneys to the north. There is a weatherboard clad lean-to at the rear. The property has a timber picket fence to the Chapman Road frontage.			
History:			
Construction Date: Architect:	Unknown	Source: Builder:	Unknown
No History Available.			
Historic Theme(s):			
HCWA:		AHC:	
104 Land allocation and	subdivision	4.1.2 Making suburbs	
Statement of Significance: This house has considerable streetscape appeal given its simple style, small scale and relatively high integrity. The aesthetic charm of the house is enhanced by the twin tall chimneys, the small entry gable and the use of weatherboard cladding.			
Management Category: 3X			
Level of Significance:			
MODERATE SIGNIFICANCE: Important to the heritage of the locality.			
Management Recomendation:			
Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible			

Supporting Information:

Other Listings: No Other Listings

Other Photos:

Wednesday, 27 January 2016 2/3

Name: House

Asset ID: G060



City of Greater Geraldton

Municipal Inventory Place Record



Photo Description:

5/12/1996 Suba & Grundy Two tall rendered chimneys punctuate the roofscape.

3/3

Wednesday, 27 January 2016 Name: House

Asset ID: G060