

Area: Geraldton	Place Number: 137	Category: 3
Assessment Date: 15/10/1996	Last Revision Date: 03/11/2009	
HCWA Number: 13387	Asset ID: MCH127075	

PLACE DETAILS

Name:	Residence
Other Names:	72-74 Fitzgerald Street
Type of Place:	Residence
Address:	72-74 Fitzgerald Street
Suburb:	Geraldton

LOCATION

Map Reference: 14.14	GPS Northing: 6814159.00	GPS Easting: 266374.000
		000



Photo Description:
10/08/2007
Rod Milne
Two semidetached houses.

SITE DETAILS

Lot No.:	Lot 1	Assess No.:	11580
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Brick	Roof:	Corrugated Iron
Condition:	Not applicable	Integrity:	
Original fabric:			
Modifications:			

This property has two identical semi detached buildings. Each painted brick building is separated by a parapet wall and has a gambrel corrugated iron roof to the rear with a separate gable to the front. The gable end has roughcast and timber infill. Below the gable a separate verandah roof joins to the central parapet wall at the centre and is hipped at each end. The verandah is supported on turned double half timber posts on brick columns. The verandah has a decorative timber arched frieze. Entry doors are situated each side of the dividing parapet wall and there is a french door with glassed surround to the verandah.

HISTORY

Construction Date:	unknown	Source:	
Architect:	Unknown		
Builder:	Unknown		

Contact John Rock for further information (PH: 9921 3269).

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision 501 World wars and other wars
--------------	--

STATEMENT OF SIGNIFICANCE

These two semidetached houses have retained much of their original fabric and style including the decorative gable ends, turned timber posts and french doors. Given this, they are representative of small semi detached houses of their era and contribute to the streetscape of the area, in particular in conjunction with 76-78 Fitzgerald Street.

MANAGEMENT CATEGORY

Management Category: 3
Level of Significance: MODERATE SIGNIFICANCE: Important to the heritage of the locality.
Management Recommendation: Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

Bibliography:
"Farmer handles shell find with extra care" The Geraldton Guardian
12/07/1996.

OTHER PHOTOS



Photo Description:
15/10/1996
Suba & Grundy
Previously used as offices.