

Area: Geraldton	Place Number: 141	Category: 3
Assessment Date: 15/10/1996	Last Revision Date: 03/11/2009	
HCWA Number: 13391	Asset ID: MCH127107	

PLACE DETAILS

Name:	House
Other Names:	83 Fitzgerald Street
Type of Place:	House
Address:	83 Fitzgerald Street
Suburb:	Geraldton

LOCATION

Map Reference: 14.14	GPS Northing: 6814094.00	GPS Easting: 266436.000
	0000	000



Photo Description:

26/06/2009

Tanya Henkel

Stone house set behind a tall rendered wall.

SITE DETAILS

Lot No.:	Lot 2	Assess No.:	11154
Reserv No.:		Vol/Fol:	1028/852
Dia/Plan:	301328		

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:	Unknown		
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Stone	Roof:	Corrugated Iron
Condition:	Good	Integrity:	
Original fabric:	Highly intact		
Modifications:	New entry door		

Located on the corner of Augustus Street, this stone house has a hipped corrugated iron roof with a separate verandah to the front (west) elevation which is supported on timber posts. To the rear there is a skillion roof with a tall corbelled chimney. The stonework is coursed with brick quoining to the original openings and corners of the building. The timber windows are a mixture of original double hung and casement. The house is set behind a tall rendered masonry wall which largely obscures the view to it from the street.

HISTORY

Construction Date:	1890	Source:	Feilman
Architect:	Unknown		
Builder:	Unknown		

This house along with the next door house are built of White Peak stone. Mrs Whitfield and her daughter lived in one and Mr Bardwell lived in the other. (Source: M. Cobley).

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

Although this house has had alterations to the windows and is set behind a tall brick wall, the roof form, stonework and tall chimney are still visible and allow the place to contribute to the streetscape of the area. The place also demonstrates the use of local materials (stone) in house construction.

MANAGEMENT CATEGORY

Management Category:	3
Level of Significance:	MODERATE SIGNIFICANCE: Important to the heritage of the locality.
Management Recommendation:	Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

Feilman & Associates, "Survey of Places of Historic and Landscape Significance in Geraldton", 1977.

OTHER PHOTOS



Photo Description:

15/10/1996

Suba & Grundy

Tall chimney punctuates the rear roof.