

Area: Geraldton	Place Number: 154	Category: 3
Assessment Date: 15/10/1996	Last Revision Date: 04/11/2009	
HCWA Number: 13404	Asset ID: MCH126705	

PLACE DETAILS

Name:	House
Other Names:	117-121 Fitzgerald Street
Type of Place:	House
Address:	117-121 Fitzgerald Street
Suburb:	Geraldton

LOCATION

Map Reference: 14.14	GPS Northing: 6813862.00	GPS Easting: 266482.000
	GPS Northing: 0000	GPS Easting: 000



Photo Description:
6/12/2007
Rod Milne
View from Fitzgerald Street.

SITE DETAILS

Lot No.:	Lot 24	Assess No.:	11140
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Stone	Roof:	Corrugated Iron
Condition:	Good	Integrity:	
Original fabric:			
Modifications:			

This is a large long stone building containing three units which is covered by a hipped corrugated iron roof. The main roof has a broken back extension which covers the front (west) verandah which is supported on timber posts. There is a brick chimney to the northern end and there is a tall brick wall to the street boundary.

HISTORY

Construction Date:	1890	Source:	Feilman
Architect:	Unknown		
Builder:	Unknown		

No History Available.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

Although partly obscured by a brick wall, the long street aspect and roof form give this place aesthetic appeal. The place is evidence of the use of local materials and makes a high contribution to the streetscape of the locale.

MANAGEMENT CATEGORY

Management Category: 3
Level of Significance: MODERATE SIGNIFICANCE: Important to the heritage of the locality.
Management Recommendation: Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

Feilman & Associates, "Survey of Places of Historic and Landscape Significance in Geraldton", 1977.

OTHER PHOTOS



Photo Description:

15/10/1996

Suba & Grundy

Long building with hipped roof.