

<b>Area:</b> Geraldton	<b>Place Number:</b> 155	<b>Category:</b> 6
<b>Assessment Date:</b> 15/10/1996	<b>Last Revision Date:</b> 04/11/2009	
<b>HCWA Number:</b> 13405	<b>Asset ID:</b> MCH126989	

### PLACE DETAILS

<b>Name:</b>	Site
<b>Other Names:</b>	118 Fitzgerald Street
<b>Type of Place:</b>	Site
<b>Address:</b>	118 Fitzgerald Street
<b>Suburb:</b>	Geraldton

### LOCATION

<b>Map Reference:</b> 14.14	<b>GPS Northing:</b> 6813862.00	<b>GPS Easting:</b> 266482.000
		000



**Photo Description:**

15/10/1996  
Suba & Grundy  
Steeply pitched roof was a feature.

## SITE DETAILS

<b>Lot No.:</b>	Lot 17	<b>Assess No.:</b>	11085
<b>Reserv No.:</b>		<b>Vol/Fol:</b>	
<b>Dia/Plan:</b>			

## USE OF PLACE

<b>Original Use:</b>	Residence		
<b>Current Use:</b>	Not Applicable		
<b>Ownership:</b>			
<b>Public Access:</b>	No	<b>Occupied:</b>	Occupied

## DESCRIPTION

<b>Walls:</b>	Weatherboard/CGI	<b>Roof:</b>	Corrugated Iron
<b>Condition:</b>	Fair	<b>Integrity:</b>	
<b>Original fabric:</b>			
<b>Modifications:</b>			

This house was demolished in 2005. The following description was contained in the 1997 Municipal Inventory: This small timber framed cottage has a steeply pitched hipped painted corrugated iron roof with corrugated iron cladding to the side walls and weatherboard to the front (east) facade. A separate verandah roof to the front elevation is supported on timber posts with a trellis balustrade and fibro infill to the verandah ends. Windows are timber framed and double hung. To the rear a lean-to roof covers a fibro clad extension.

## HISTORY

<b>Construction Date:</b>	1890	<b>Source:</b>	Feilman
<b>Architect:</b>	Unknown		
<b>Builder:</b>	Unknown		

The house was demolished in 2005.

## HISTORIC THEMES

<b>HCWA:</b>	104 Land allocation and subdivision 300 Occupations
<b>AHC:</b>	4.1.2 Making suburbs

### STATEMENT OF SIGNIFICANCE

There were few examples remaining of this simple style of corrugated iron and weatherboard clad cottage. Further, this place had high integrity and its form contributed to the streetscape of the area.

1997 Management Category: 3. SIGNIFICANT AS AN INDIVIDUAL BUILDING. Retain and conserve if possible: endeavour to conserve the significance of the place through provisions of the Town Planning Scheme. Photographically record the place prior to any major redevelopment.

### MANAGEMENT CATEGORY

**Management Category:** 6

**Level of Significance:** MUNICIPAL INVENTORY ARCHIVE: Place was previously included in the Municipal Inventory but has been removed due to demolition or diminished heritage significance.

**Management Recommendation:** The place does not form part of the relevant local Town Planning Scheme Heritage List. This category is for record keeping purposes only.

### OTHER LISTINGS

No other listings

### SUPPORTING INFORMATION

Bibliography:  
HCWA Database No. 13902.

### OTHER PHOTOS

No other photos