

<b>Area:</b> Geraldton	<b>Place Number:</b> 156	<b>Category:</b> 2
<b>Assessment Date:</b> 15/10/1996	<b>Last Revision Date:</b> 04/11/2009	
<b>HCWA Number:</b> 13406	<b>Asset ID:</b> MCH127014	

### PLACE DETAILS

<b>Name:</b>	House
<b>Other Names:</b>	124 Fitzgerald Street
<b>Type of Place:</b>	House
<b>Address:</b>	124 Fitzgerald Street
<b>Suburb:</b>	Beachlands

### LOCATION

<b>Map Reference:</b> 14.14	<b>GPS Northing:</b> 6813832.00	<b>GPS Easting:</b> 266403.000
	<b>GPS Northing:</b> 0000	<b>GPS Easting:</b> 000



**Photo Description:**

3/12/2007

Rod Milne

Decorative verandah posts, braces and frieze.

## SITE DETAILS

<b>Lot No.:</b>	Lot 1	<b>Assess No.:</b>	11087
<b>Reserv No.:</b>		<b>Vol/Fol:</b>	
<b>Dia/Plan:</b>			

## USE OF PLACE

<b>Original Use:</b>	Residence		
<b>Current Use:</b>	Residence		
<b>Ownership:</b>			
<b>Public Access:</b>	No	<b>Occupied:</b>	Occupied

## DESCRIPTION

<b>Walls:</b>	Brick	<b>Roof:</b>	Aluminium Tile
<b>Condition:</b>	Good	<b>Integrity:</b>	
<b>Original fabric:</b>			
<b>Modifications:</b>	Roof reclad		

This large house has an aluminium tiled gambrel roof which extends to cover verandahs on three sides. The verandahs are supported on turned timber posts with timber brackets to a small baluster frieze. A small gable to the front verandah enhances the entrance. The face red brick is tuckpointed and has a rendered band at half window height which extends to form an arch above the recessed entry. Windows are timber framed and double hung. There are three rendered corbelled chimneys, two also have terracotta chimney pots. A timber picket fence forms the street boundary of the property.

## HISTORY

<b>Construction Date:</b>	unknown	<b>Source:</b>	Heritage Trail
<b>Architect:</b>	Unknown		
<b>Builder:</b>	Unknown		

No History Available.

## HISTORIC THEMES

<b>HCWA:</b>	104 Land allocation and subdivision 400 Social and civic activities
--------------	--

**AHC:** 503 Natural disasters  
4.1.2 Making suburbs  
3.16.1 Dealing with hazards and disasters

### STATEMENT OF SIGNIFICANCE

This house has high integrity given the retention of its decorative elements such as the turned timber posts, tall corbelled chimney and banded face brickwork. Further the place has high aesthetic appeal and makes a major contribution to the streetscape of the locale.

### MANAGEMENT CATEGORY

**Management Category:** 2  
**Level of Significance:** CONSIDERABLE SIGNIFICANCE: Very important to the heritage of the locality.  
**Management Recommendation:** Conservation of the place is highly recommended. Any proposed change should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

### OTHER LISTINGS

No other listings

### SUPPORTING INFORMATION

Bibliography:  
Greenough-Walkaway Heritage Trail.  
HCWA Database No. 13923.  
Extra photo inserted

### OTHER PHOTOS



**Photo Description:**

15/10/1996

Suba & Grundy

Entry enhanced by roof gable.