

Area: Geraldton	Place Number: 201	Category: 3
Assessment Date: 05/11/1996	Last Revision Date: 24/11/2009	
HCWA Number: 13298	Asset ID: MCH126949	

PLACE DETAILS

Name:	House
Other Names:	260 George Road
Type of Place:	House
Address:	260 George Road
Suburb:	Beresford

LOCATION

Map Reference: 15.18	GPS Northing: 6817296.00	GPS Easting: 267685.000
		000



Photo Description:

31/07/2007

Rod Milne

Large roof dominates the house.

SITE DETAILS

Lot No.:	Lot 51	Assess No.:	18230
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Stone	Roof:	Corrugated Iron
Condition:	Good	Integrity:	
Original fabric:			
Modifications:			

This stone building has steeply pitched hipped corrugated iron roof with small gablets to the east and west and a tall chimney to the west. The main roof extends to cover the surrounding verandahs which are supported on metal poles with decorative brackets. The verandahs have some brick infill to the south east. The stonework is coursed and pointed with red brick quoining to the openings and corners. Windows are timber framed and double hung with french doors to the verandah. The street boundary has a low stone wall.

HISTORY

Construction Date:	unknown	Source:	
Architect:	Unknown		
Builder:	Unknown		

No History Available.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision 603 Local heroes and battlers 602 Early settlers
--------------	--

AHC: 4.1.2 Making suburbs
6.5 Educating people in remote places

STATEMENT OF SIGNIFICANCE

This house has considerable aesthetic appeal given the use of local materials and built elements such as the brick quoining, french windows and surrounding verandahs. The place is unique in this locale. (The place may have historic significance if it was established before the area was subdivided.)

MANAGEMENT CATEGORY

Management Category: 3
Level of Significance: MODERATE SIGNIFICANCE: Important to the heritage of the locality.
Management Recommendation: Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

Shire of Greenough - Town Planning Scheme (65), 01/01/1970
National Trust of WA - Recorded, 01/01/1970

SUPPORTING INFORMATION

Bibliography:
Feilman, M., "Greenough Historical Survey of the Front Flats", 1977 (65).
Oral History with Leslie George Knapp conducted by Carol Cahill, 6 June 1989, OH2463 BL.
"Historic school ruin destroyed," The Geraldton Guardian 8/01/1993.
Suba, T., "The Greenough Front Flats Bibliography of Local Sources and Table of Heritage Places", 1994.
HCWA Database No. 3739.
Photographs:
GHS1223 school students (n.d.), GHS1450 school students (n.d.).

OTHER PHOTOS



Photo Description:

5/11/1996

Suba & Grundy

Surrounding verandahs a feature.