

Area: Geraldton	Place Number: 246	Category: 4
Assessment Date: 14/10/1996	Last Revision Date: 27/11/2009	
HCWA Number: 13416	Asset ID: MCH126581	

PLACE DETAILS

Name:	House
Other Names:	130 Gregory Street
Type of Place:	House
Address:	130 Gregory Street
Suburb:	Beachlands

LOCATION

Map Reference: 14.14	GPS Northing: 6813646.00	GPS Easting: 266301.000
		000



Photo Description:

21/12/2007

Rod Milne

Decorative timber bargeboarding to gable end.

SITE DETAILS

Lot No.:	Lot 21	Assess No.:	11006
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Brick	Roof:	Corrugated Iron
Condition:	Good	Integrity:	
Original fabric:			
Modifications:	Some verandah infills		

This painted brick house has a white hipped colorbond roof with a separate gable roof to the front (east) elevation which covers the main room. The gable end has fibro and batten infill with consoles to the eaves. The main roof has a hipped broken back extension which covers verandahs to the front and north of the place. The front verandah is supported on timber posts, the north east corner and north sides are enclosed with fibro. Below the gable, a corrugated iron awning covers the window to the main room. Windows to the house are small pane timber framed casement style, with aluminium framed windows to the verandah infill. Access to the verandah is via steps with metal balustrade. A low asbestos fence with a picket gate forms the street boundary.

HISTORY

Construction Date:	1928	Source:	Rates Records
Architect:	Unknown		
Builder:	Unknown		

Rates Records indicate that in 1918 this land was owned by the Agricultural Society and the house was built c1928 for Thomas Greenaway. In the early 1930s until 1945 the Green's lived in this house, and possibly owned it.
(Source: Stan Gratte)

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

Although having alterations, this small house retains much of its original form and decorative elements to the gable end. It enhances the streetscape of the area.

MANAGEMENT CATEGORY

Management Category:	4
Level of Significance:	SOME SIGNIFICANCE: Contributes to the heritage and/or historical development of the locality.
Management Recommendation:	Conservation of the place is desirable. Any proposed change to the place should be in sympathy with the heritage values of the place.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

OTHER PHOTOS



Photo Description:

14/10/1996

Suba & Grundy

Awning to front window.