

Area: Geraldton	Place Number: 343	Category: 6
Assessment Date: 24/10/1996	Last Revision Date: 11/03/2010	
HCWA Number: 13735	Asset ID: MCH126811	

PLACE DETAILS

Name:	Site
Other Names:	5 Sanford Street
Type of Place:	Site
Address:	5 Sanford Street
Suburb:	Geraldton

LOCATION

Map Reference: 15.15	GPS Northing: 6814915.00	GPS Easting: 267159.000
	GPS Easting: 0000	GPS Northing: 000



Photo Description:

24/10/1996

Suba & Grundy

House hidden behind two palm trees.

SITE DETAILS

Lot No.:	Lot 48	Assess No.:	11658
Reserv No.:		Vol/Fol:	

USE OF PLACE

Original Use:	Residence	Occupied:	Not Occupied
Current Use:	Not Applicable		
Ownership:			
Public Access:	No		

DESCRIPTION

Walls:	Weatherboard	Roof:	Corrugated Iron
Condition:	Not applicable	Integrity:	
Original fabric:			
Modifications:			

The house was demolished in c2000. The following description is from the 1997 City of Geraldton Municipal Inventory: This house is set above the street level and has two large palm trees (Washingtonia robusta) directly in front of it. The timber framed house has weatherboard cladding. There is a hipped corrugated iron roof which has a separate gable to the main room and separate verandah roof to the front (west) elevation. The verandah is supported on timber posts and has lattice infill above a fibro balustrade. There is a lean-to roof to the rear and windows are timber framed and double hung.

HISTORY

Construction Date:	unknown	Source:	
Architect:	Unknown		
Builder:	Unknown		

No History Available.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

Although partly concealed by vegetation, the house contributed to the streetscape given that it retained much of its original fabric. Further it was representative of the style of housing of its era.

1997 Management Category: 3. SIGNIFICANT AS AN INDIVIDUAL BUILDING. Retain and conserve if possible: endeavour to conserve the significance of the place through provisions of the Town Planning Scheme. Photographically record the place prior to any major redevelopment.

MANAGEMENT CATEGORY

Management Category: 6

Level of Significance: MUNICIPAL INVENTORY ARCHIVE: Place was previously included in the Municipal Inventory but has been removed due to demolition or diminished heritage significance.

Management Recommendation: The place does not form part of the relevant local Town Planning Scheme Heritage List. This category is for record keeping purposes only.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

GLLSPC - Geraldton General

OTHER PHOTOS

No other photos