

Area: Geraldton	Place Number: 367	Category: 3
Assessment Date: 24/10/1996	Last Revision Date: 12/03/2010	
HCWA Number: 13761	Asset ID: MCH126536	

PLACE DETAILS

Name:	House
Other Names:	113 Shenton Street
Type of Place:	House
Address:	113 Shenton Street
Suburb:	Geraldton

LOCATION

Map Reference: 14.14	GPS Northing: 6813759.00	GPS Easting: 266563.000
	0000	000



Photo Description:
30/11/2007
Rod Milne
Carport to front garden.

SITE DETAILS

Lot No.:	Lot 2	Assess No.:	10441
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:	Western Australian Government		
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Weatherboard	Roof:	Corrugated Iron
Condition:	Good	Integrity:	
Original fabric:	Stone walls		
Modifications:	Partial verandah infill		

This timber framed weatherboard clad house also has some replacement fibro cladding. Its corrugated iron gambrel roof extends to cover the front verandah which is supported on timber posts. Windows are timber framed and double hung with a metal awning over the front window. There is a rendered corbelled chimney. A double carport is sited to the front garden and a picket fence forms the street boundary.

HISTORY

Construction Date:	unknown	Source:	Register Documentation
Architect:	Unknown		
Builder:	Unknown		

No History Available.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision 605 Famous and infamous people
AHC:	4.1.2 Making suburbs

STATEMENT OF SIGNIFICANCE

This house has retained many of its original features including the weatherboard cladding, timber windows and decorative door surround. The place is representative of weatherboard houses of its era and contributes to the streetscape of the area.

MANAGEMENT CATEGORY

Management Category: 3
Level of Significance: MODERATE SIGNIFICANCE: Important to the heritage of the locality.
Management Recommendation: Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

Heritage Council of WA - Register, 20/02/2004
National Trust of WA - Classified, 07/03/1995

SUPPORTING INFORMATION

Feilman & Associates, "Survey of Places of Historic and Landscape Significance in Geraldton", 1977.
Uhe, P., "Survey of Railway Heritage in WA", National Trust of WA, 1994.

OTHER PHOTOS



Photo Description:

24/10/1996

Suba & Grundy

View of house partly obscured by vegetation.